1/6

FIG.1

Formation of Sensor and Actuator Element Material by Liquid Rapid Solidification Method (Formation of Thin Belt and Thin Wire: Fine Columnar Crystal Texture, Large Crystalline Anisotropy, Non-Equilibrium Phase)




FIG.2




FIG.3







FIG.4



3/6









4/6









16.9




FIG.10

